Getinge Assured



Bowie-Dick Test Card TT Interpretation Guide

Unexposed



Pass



Complete colour change from purple to green, indicates that an effective steam sterilization cycle has been achieved.

Fail



This is an example of one type of fail. Any remaining purple indicates a fail.